

# CONSTRUCTION EQUIPMENT X18242 APAC VOLVO A40G 353065 - DIESEL ENGINE



Sample No: VCP441534

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

**Job No:** X18242 APAC

Boron

ppm

Report Id: VOLVO8771 [WUSCAR] 06079513 (Generated: 02/07/2024 14:34:00) Rev: 1

VOLVO				
SAMPLE IN	NFORMATION			
Sample Number	-	VCP441534		 
Sample Date		30 Jan 2024		 
Machine Hours		3128		 
Oil Hours		0		 
Oil Changed		Changed		 
Sample Status		NORMAL		 
OIL CONDI.	TION			
Visc @ 100°C	cSt	<b>12.4</b>		 
Base Number (BN)	mg KOH/g	<b>7.9</b>		 
Oxidation (PA)	%	84		 
VOLVO	IATION			
CONTAMIN				
Water	%	NEG		 
Soot %	%	■ 0.3		 
Nitration (PA)	%	83		 
Sulfation (PA)	%	63		 
Glycol	%	NEG		 
Fuel	%	■0.8		 
Silicon	ppm	<b>12</b>		 
Sodium	ppm	<b>■</b> 5		 
Potassium	ppm	<b>□</b> 0		 
VOLVO				
WEAR ME	TALS			
Iron	ppm	<b>11</b>		 
Copper	ppm	9		 
Lead	ppm	<b></b>		 
Tin	ppm	1		 
Aluminum		<b>6</b>		 
Chromium	ppm	<b>0</b>		 
Molybdenum	ppm	<b>45</b>		 
Nickel	ppm	<b></b>		 
Titanium	ppm	0		 
Silver	ppm	0		 
Manganese	ppm	<b>■</b> <1		 
Vanadium	ppm	0		 
	77			
ADDITIVES				
Calcium	ppm	<b>1747</b>		 
Magnesium	ppm	<b>■ 523</b>		 
Zinc		■1146		 
Phosphorus	ppm	<b>985</b>		 
Barium		<b>0</b>		 
Dullulli	ppm		-	



#### **SCOTT EQUIPMENT COMPANY LLC - Jackson**

3860 I-55 South JACKSON, MS US 39212

Contact: DWIGHT MCDOUGAL DMCDOUGAL@SCOTTCOMPANIES.COM

T:

F: (601)326-3359

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

 Depot:
 VOLVO8771

 Unique No:
 10861604

 Signed:
 Wes Davis

 Report Date:
 07 Feb 2024



## **CONSTRUCTION EQUIPMENT**





