

## **CONSTRUCTION EQUIPMENT**

646452 MOSAIC CO VOLVO A45G 352974 - HYDRAULIC SYSTEM

Sample No: VCP432025

Silicon

Sodium

Potassium

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

**Job No:** 646452 MOSAIC CO

ppm

ppm

ppm

**6** 

**0** 

**0** 



WEAR METALS								
WLAIN	IL I VES							
Iron	ppm	<b>0</b>						
Copper	ppm	<b>■&lt;1</b>						
Lead	ppm	<b>2</b>						
Tin	ppm	■0						
Aluminum	ppm	<b>1</b>						
Chromium	ppm	<b>■&lt;1</b>						
Molybdenum	ppm	<b>■&lt;1</b>						
Nickel	ppm	■0						
Titanium	ppm	0						
Silver	ppm	0						
Manganese	ppm	<b>0</b>						
Vanadium	ppm	0						

ADDITIVES									
Calcium	ppm	<b>104</b>							
Magnesium	ppm	■8							
Zinc	ppm	<b>430</b>							
Phosphorus	ppm	■324							
Barium	ppm	<b>0</b>							
Boron	ppm	■0							



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0093Unique No:10861817Signed:Wes DavisReport Date:06 Feb 2024



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

