

CONSTRUCTION EQUIPMENT 658972 VOLVO ECR145E 311261 - SWING DRIVE



Sample No: VCP452341

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 658972

SAMPLE	INFORMATION			
Sample Number		VCP452341	VCP311985	
Sample Date		04 Jan 2024	12 May 2021	
Machine Hours		2833	1858	
Oil Hours		1000	1000	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	ABNORMAL	
VOLVO	DITION			
OIL CON		<u> </u>		
Visc @ 40°C	cSt	254	189	
VOLVO				
LUNTAN	IINATION			
_		NEC	NEC	<u> </u>
Water	%	NEG	NEG	
Silicon	ppm	6	12	
Sodium	ppm		2	
Potassium	ppm	■ <1		
VOLVO				
WEAR M	IETALS			
Iron	ppm	117	□ 503	
Copper	ppm	2 1	1 50	
Lead	ppm			
Tin	ppm	-<1	<1	
Aluminum	ppm	1	2	
Chromium	ppm	1	5	
Molybdenum	ppm	2		
Nickel	ppm	■<1	<1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	2	1 0	
Vanadium	ppm	<1	0	
ADDITIV	71			
_	-	-120	m 12	
Calcium	ppm	139	13	
Magnesium	ppm	67	0	
Zinc	ppm	104	102	
Phosphorus	ppm	893	445	
Barium	ppm	0	0	
Boron	mag	132	7	



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com

1: F:

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10862336Signed:Wes DavisReport Date:06 Feb 2024



CONSTRUCTION EQUIPMENT





