

## **CONSTRUCTION EQUIPMENT**

639020 TUCKER PAVING VOLVO EC550EL 310196 - RIGHT SWING DRI

Sample No: VCP428862

Silicon

Sodium

Potassium

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**32** 

**0** 

**-<1** 

**Job No:** 639020 TUCKER PAVING

ppm

ppm

ppm

SAMPLE I	NFORMATION					
Sample Number	-	VCP428862				
Sample Date		05 Jan 2024				
Machine Hours		1236				
Oil Hours		1236				
Oil Changed		Changed				
Sample Status		NORMAL				
OIL CONDITION						
Visc @ 40°C	cSt	<b>171</b>				
CONTAMI	NATION					
Water	%	NEG				

WEAR METALS								
WEAK WEIGHT								
Iron	ppm	<b>120</b>						
Copper	ppm	■39						
Lead	ppm	<b>■&lt;1</b>						
Tin	ppm	<b>■&lt;1</b>						
Aluminum	ppm	<b>2</b>						
Chromium	ppm	<b>2</b>						
Molybdenum	ppm	<b>-&lt;1</b>						
Nickel	ppm	<b>■&lt;1</b>						
Titanium	ppm	<1						
Silver	ppm	0						
Manganese	ppm	<b>4</b>						
Vanadium	ppm	0						

ADDITIVES							
Calcium	ppm	<b>27</b>					
Magnesium	ppm	■0					
Zinc	ppm	■34					
Phosphorus	ppm	■357					
Barium	ppm	<b>0</b>					
Boron	ppm	<b>1</b>					



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10862343Signed:Don BaldridgeReport Date:07 Feb 2024



## **CONSTRUCTION EQUIPMENT**





