

Sample No: VCP428792
Oil Type: VOLVO AT 102
Job No: 660078 MOSAIC

SAMPLE	INFORMATIO	N		
Sample Number		VCP428792	VCP0007637	
Sample Date		12 Jan 2024	06 Jun 2023	
Machine Hours		5024	0	
Oil Hours		1500	0	
Oil Changed		Not Changd	N/A	
Sample Status		NORMAL	NORMAL	
VOLVO	DITION			
OIL CON				
Visc @ 40°C	cSt	28.8	■30.1	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon		™3	112	
Sodium	ppm	3 _ 2	3	
Potassium	ppm	0	<1	
rotassiuiii	ppm			
VOLVO				
WEAR N	METALS			
Iron	ppm	■ 8	□15	
Copper	ppm	5	1 4	
Lead	ppm	0	0	
Tin	ppm	1	2	
Aluminum	ppm	4	6	
Chromium	ppm	■ 0	0	
Molybdenum	ppm	0	0	
Nickel	ppm	■ 0	_2	
Titanium	ppm	0	0	
Silver	ppm	■ 0	0	
Manganese	ppm	0	<1	
Vanadium	ppm	0	0	
ADDITIV	JFS			
_	<u> </u>		22	
Calcium	ppm	■ 62	33	
Magnesium	ppm	□ 0	0	
Zinc	ppm	■ 0	0	
Phosphorus	ppm	206	217	
Barium	ppm	0	0	
Boron	ppm	100	107	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0093Unique No:10862389Signed:Don BaldridgeReport Date:07 Feb 2024



CONSTRUCTION EQUIPMENT





