



CONSTRUCTION EQUIPMENT

SW-29338-2 VOLVO L120H 633492 - FRONT AXLE



Sample No: VCP438051
Oil Type: VOLVO WB 102
Job No: SW-29338-2



SAMPLE INFORMATION

Sample Number	VCP438051	---	---	---
Sample Date	01 Feb 2024	---	---	---
Machine Hours	1045	---	---	---
Oil Hours	1045	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ARNOLD MACHINERY COMPANY
 2975 WEST 2100 SOUTH
 SALT LAKE CITY, UT
 US 84119
 Contact: TONY PAYAN
 tpayan@arnoldmachinery.com
 T: (801)972-4000
 F: (801)975-9434



OIL CONDITION

Visc @ 40°C	cSt	█ 44.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 30	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 5	---	---	---



WEAR METALS

Iron	ppm	█ 321	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 4	---	---	---
Molybdenum	ppm	█ 15	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 13	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3826	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1560	---	---	---
Phosphorus	ppm	█ 1357	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 137	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8770
Unique No: 10871374
Signed: Wes Davis
Report Date: 09 Feb 2024



CONSTRUCTION EQUIPMENT



GRAPHS

