



CONSTRUCTION EQUIPMENT

VOLVO L110H 632644 - TRANSMISSION (AUTO)



Sample No: VCP431787

Oil Type: DEXRON III

Job No:



SAMPLE INFORMATION

Sample Number	VCP431787	---	---	---
Sample Date	04 Dec 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

COVANTA

350 FLAKENBURG ROAD
TAMPA, FL
US 33619
Contact: SERVICE MANAGER



OIL CONDITION

Visc @ 40°C	cSt	█ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----

T: (813)684-5688
F:



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 7	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 52	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 63	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 9	---	---	---
Phosphorus	ppm	█ 195	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 82	---	---	---

Depot: COVTAM
Unique No: 10871472
Signed: Don Baldrige
Report Date: 11 Feb 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

