

CONSTRUCTION EQUIPMENT VOLVO EC480 315364 - FRONT RIGHT FINAL DRIVE



Sample No: VCP430277 **Oil Type:** VOLVO GEAR

Job No:

SAMPLE	INFORMATION			
Sample Number		VCP430277	 	
Sample Date		30 Jan 2024	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	171	 	
VOLVO	4115 21611			
LUNIAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	10	 	
Sodium	ppm	0	 	
Potassium	ppm	2	 	
WEAR N	AETAL C			
_	JE I ALS			
Iron	ppm	■234	 	
Copper	ppm	■<1	 	
Lead	ppm	■ <1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	2	 	
Molybdenum	ppm	<1	 	
Nickel	ppm	1	 	
Titanium	ppm	■<1	 	
Silver	ppm	0	 	
Manganese	ppm	3	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium		5	 	
Magnesium	ppm	<1	 	
Zinc	ppm	0	 	
Phosphorus	ppm	227		
	ppm			
Barium	ppm	0	 	
Boron	ppm	<1	 	



COWIN EQUIPMENT COMPANY

P.O. DRAWER 9367 MONTGOMERY, AL US 36108 Contact: BRYAN DICKS bdicks@cowin.com T: (334)262-6642 F: (334)269-1514

Diagnosis

We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor. High concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8532Unique No:10872522Signed:Don BaldridgeReport Date:12 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPH

