



CONSTRUCTION EQUIPMENT

A11930 VOLVO EC350E 314672 - REAR LEFT FINAL DRIVE



Sample No: VCP439447
Oil Type: MOBIL MOBILUBE HD 80W90
Job No: A11930



SAMPLE INFORMATION

Sample Number	VCP439447	---	---	---
Sample Date	23 Jan 2024	---	---	---
Machine Hours	1925	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

WASTE MANAGEMENT - TELFORD

400 PROGRESS DR
 TELFORD, PA
 US 18969-1191
 Contact: EDWARD ROGENER
 erogener@wm.com
 T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 171	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 6	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 202	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 8	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 10	---	---	---
Phosphorus	ppm	█ 278	---	---	---
Barium	ppm	█ 1	---	---	---
Boron	ppm	█ 0	---	---	---

Depot: WASTEL
Unique No: 10873742
Signed: Sean Felton
Report Date: 13 Feb 2024



CONSTRUCTION EQUIPMENT



GRAPHS

