

## **CONSTRUCTION EQUIPMENT**

SPM646179 SENNEBOGEN 835 835.0.3282 - REAR RIGHT FINAL DRIVE

Sample No: VCP436919

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SPM646179

Potassium

VOLVO							
	NFORMATION						
Sample Number	•	VCP436919					
Sample Date		08 Dec 2023					
Machine Hours		223					
Oil Hours		0					
Oil Changed		Changed					
Sample Status		NORMAL					
OIL CONDITION							
Visc @ 40°C	cSt	<b>181</b>					
CONTAMINATION							
Water	%	NEG					
Silicon	ppm	<b>■</b> 3					
Sodium	ppm	<b>2</b>					

VOLVO				
WEAR I	METALS			
Iron	ppm	<b>75</b>	 	
Copper	ppm	<b>19</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>0</b>	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b>	 	
Vanadium	ppm	0	 	

ADDITIVES						
Calcium	ppm	<b>11</b>				
Magnesium	ppm	<b>□</b> 0				
Zinc	ppm	<b>12</b>				
Phosphorus	ppm	<b>1189</b>				
Barium	ppm	<b>364</b>				
Boron	ppm	<b>13</b>				



## BELSON STEEL 1685 N STATE RTE 50 BOURBONNAIS, IL US 60914 Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416 F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:BELBOUUnique No:10873765Signed:Wes DavisReport Date:13 Feb 2024

Contact/Location: M. POZAN - BELBOU



## **CONSTRUCTION EQUIPMENT**





