CONSTRUCTION EQUIPMENT 3591 BULK EXPRESS VOLVO L 150H 6957 - FRONT AXLE

Sample No:VCP441778Oil Type:TDH FLUID SAE 75W80Job No:3591 BULK EXPRESS

VOLVO

	INFORMATION			
Sample Number		VCP441778	 	
Sample Date		07 Feb 2024	 	
Machine Hours		7032	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	42.5	 	
VOLVO			 	
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	1 3	 	
Sodium	ppm	3	 	
Potassium	ppm	0	 	
WEAR N				
Iron	ppm	25	 	
Copper	ppm	0	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	1	 	
Chromium	ppm	□ <1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	■0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
VOLVO			 	
ADDITIN	VES		 	
Calcium	ppm	3579	 	
Magnesium	ppm	29	 	



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO0096		
Unique No:	10873844		
Signed:	Don Baldridge		
Report Date:	13 Feb 2024		

1464

1246

0 137

ppm

ppm

ppm

ppm

Zinc

Barium

Boron

Phosphorus


Contact/Location: Robert LaPlante - VOLVO0096

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0096 [WUSCAR] 06086399 (Generated: 02/13/2024 18:41:40) Rev: 1

Contact/Location: Robert LaPlante - VOLVO0096