



# CONSTRUCTION EQUIPMENT

## 685 VOLVO L150H 7148 - REAR AXLE



**Sample No:** VCP359796  
**Oil Type:** MOBIL DELVAC 1 TRANSMISSION 75W80  
**Job No:** 685



### SAMPLE INFORMATION

Sample Number	VCP359796	---	---	---
Sample Date	02 Feb 2024	---	---	---
Machine Hours	1111	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**VCES- VOLVO CONSTRUCTION EQUIPMENT**  
 12345 MAPLEVIEW STREET  
 LAKESIDE, CA  
 US 92040  
 Contact: Mark Stewart  
 mark.stewart@vcesvolvo.com  
 T: X  
 F: X



### OIL CONDITION

Visc @ 40°C	cSt	█ 40.8	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 9	---	---	---
Potassium	ppm	█ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 24	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	█ 3830	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 1560	---	---	---
Phosphorus	ppm	█ 1172	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 125	---	---	---

**Depot:** VOLVO4488  
**Unique No:** 10875193  
**Signed:** Jonathan Hester  
**Report Date:** 15 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

