



# CONSTRUCTION EQUIPMENT

0164488 VOLVO 622812 - COOLANT



**Sample No:** VCP428600  
**Oil Type:** EXTENDED LIFE COOLANT  
**Job No:** 0164488



## SAMPLE INFORMATION

Sample Number	VCP428600	---	---	---
Sample Date	08 Jan 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

**ROMCO INC**  
 1350 NE LOOP 820  
 FORT WORTH, TX  
 US 76106  
 Contact: ROB HOLCOMB  
 rholcomb@romco.com  
 T: (817)798-9289  
 F: (817)626-8983



## COOLANT CONDITION

pH	Scale 0-14	■ 7.59	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 51.1	---	---	---
Freezing Point	°C	■ -38	---	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

**Depot:** VOLVO0081  
**Unique No:** 10875336  
**Signed:** Jonathan Hester  
**Report Date:** 15 Feb 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

