CONSTRUCTION EQUIPMENT SWA478970-10 SACYR VOLVO A40G 353255 - DIESEL ENGINE

 Sample No:
 VCP442803

 Oil Type:
 {unknown}

 Job No:
 SWA478970-10 SACYR

TOTATO

	FORMATION								
					-				
Sample Number		VCP442803							
Sample Date		07 Feb 2024							
Machine Hours		1763							
Oil Hours		0							
Oil Changed		N/A							
Sample Status		ABNORMAL							
VOLVO									
Visc @ 100°C	cSt	<b>10.7</b>							
Base Number (BN)	mg KOH/g	3.9							
Oxidation (PA)	%	69							
VOLVO									
Contamin	VATION								
Water	%	NEG							
Soot %	%	0.3							
Nitration (PA)	%	88							
Sulfation (PA)	%	69							
Glycol	%	NEG							
Fuel	%	0.6							
Silicon	ppm	<u> </u>							
Sodium	ppm	<b>4</b>							
Potassium	ppm	3							
WEAR ME	TALS								
Iron	-	27							
Copper	ppm	164							
Lead	ppm	■ 104 ■ <1							
Tin	ppm								
Aluminum	ppm	3							
Chromium	ppm								
	ppm	■ <1							
Molybdenum	ppm	81							

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

We advise that you check the air filter, air induction system, and any areas where dirt may enter the component. The filter change at the time of sampling has been noted. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.Metal levels are typical for a new component breaking in. Fuel content negligible. Elemental level of silicon (Si) above normal indicating ingress of dirt/seal material. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Manganese	ppm	3							
Vanadium	ppm	0							
ADDITIVES									
Calcium	ppm	2088							
Magnesium	ppm	<b>4</b> 3							
Zinc	ppm	<b>1170</b>							
Phosphorus	ppm	985							
Barium	ppm	□<1							
Boron	ppm	9							

 Depot:
 VOLVO0093

 Unique No:
 10875356

 Signed:
 Doug Bogart

 Report Date:
 15 Feb 2024

Report Id: VOLVO0093 [WUSCAR] 06087911 (Generated: 02/16/2024 01:14:30) Rev: 1

2

0

0

ppm

ppm

ppm

Nickel

Silver

Titanium


Contact/Location: KENNY HANEY - VOLVO0093

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06087911 (Generated: 02/16/2024 01:14:32) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093