



# CONSTRUCTION EQUIPMENT

## 12058 VOLVO A30D 12117 - REAR AXLE



**Sample No:** VCP443153  
**Oil Type:** MOBIL MOBILUBE HD PLUS 85W140  
**Job No:** 12058



### SAMPLE INFORMATION

Sample Number	<b>VCP443153</b>	VCP374832	VCP374833	VCP283841
Sample Date	<b>08 Feb 2024</b>	11 Aug 2022	09 Aug 2022	10 Aug 2020
Machine Hours	<b>12796</b>	10465	10465	11690
Oil Hours	<b>0</b>	2000	2000	1500
Oil Changed	<b>N/A</b>	Changed	Changed	Not Changd
Sample Status	<b>ABNORMAL</b>	NORMAL	NORMAL	NORMAL

**JAMES J ANDERSON**  
 6958 TORRESDALE AVENUE  
 PHILADELPHIA, PA  
 US 19135  
 Contact: JOHN HERBUT  
 herb@jjaconstruction.com  
 T: (215)850-9051  
 F: (215)427-0208

### OIL CONDITION

Visc @ 40°C	cSt	<b>280</b>	263	312	261
-------------	-----	------------	-----	-----	-----

### CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	<b>20</b>	22	9	24
Sodium	ppm	<b>0</b>	4	<1	4
Potassium	ppm	<b>2</b>	<1	2	<1

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

### WEAR METALS

Iron	ppm	<b>52</b>	81	61	71
Copper	ppm	<b>2</b>	4	5	4
Lead	ppm	<b>0</b>	0	<1	0
Tin	ppm	<b>0</b>	<1	<1	0
Aluminum	ppm	<b>4</b>	5	1	2
Chromium	ppm	<b>&lt;1</b>	<1	<1	0
Molybdenum	ppm	<b>1</b>	4	<1	4
Nickel	ppm	<b>0</b>	<1	0	<1
Titanium	ppm	<b>&lt;1</b>	<1	<1	<1
Silver	ppm	<b>0</b>	0	<1	<1
Manganese	ppm	<b>&lt;1</b>	<1	<1	<1
Vanadium	ppm	<b>0</b>	0	0	0

### ADDITIVES

Calcium	ppm	<b>107</b>	205	30	180
Magnesium	ppm	<b>10</b>	20	7	16
Zinc	ppm	<b>37</b>	110	27	94
Phosphorus	ppm	<b>1371</b>	881	1038	891
Barium	ppm	<b>12</b>	<1	2	0
Boron	ppm	<b>217</b>	161	213	217

**Depot:** JAAPHI  
**Unique No:** 10876595  
**Signed:** Jonathan Hester  
**Report Date:** 16 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

