



# CONSTRUCTION EQUIPMENT

SPM658877 VOLVO A25G 752898 - FRONT AXLE



**Sample No:** VCP429128  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM658877



## SAMPLE INFORMATION

Sample Number	VCP429128	---	---	---
Sample Date	10 Jan 2023	---	---	---
Machine Hours	567	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	ATTENTION	---	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
 5000 INDUSTRIAL HWY  
 GARY, IN  
 US 46406  
 Contact: DAVE ENG  
 DAVE.ENG@ALTG.COM  
 T: (312)350-2560  
 F:



## OIL CONDITION

Visc @ 40°C	cSt	▲ 87.2	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 5	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 5	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.



## WEAR METALS

Iron	ppm	■ 264	---	---	---
Copper	ppm	■ 24	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 5	---	---	---
Molybdenum	ppm	■ 6	---	---	---
Nickel	ppm	■ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	<1	---	---	---
Manganese	ppm	■ 9	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	■ 799	---	---	---
Magnesium	ppm	■ 4	---	---	---
Zinc	ppm	■ 366	---	---	---
Phosphorus	ppm	■ 1312	---	---	---
Barium	ppm	■ 2	---	---	---
Boron	ppm	■ 239	---	---	---

**Depot:** VOLVO8885  
**Unique No:** 10883403  
**Signed:** Don Baldrige  
**Report Date:** 17 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

