



CONSTRUCTION EQUIPMENT

SPM608314 VOLVO EC380EL 311492 - RIGHT FINAL DRIVE



Sample No: VCP426432
Oil Type: GEAR OIL SAE 80W90
Job No: SPM608314



SAMPLE INFORMATION

Sample Number	VCP426432	VCP414192	VCP403424	VCP312885
Sample Date	15 Sep 2023	21 Jul 2023	28 Feb 2023	09 Mar 2022
Machine Hours	7993	7780	6944	5012
Oil Hours	0	0	0	0
Oil Changed	Changed	Not Chngd	Changed	Changed
Sample Status	ABNORMAL	NORMAL	ABNORMAL	ABNORMAL

BELSON STEEL
 1685 N STATE RTE 50
 BOURBONNAIS, IL
 US 60914
 Contact: M. POZAN
 mpozan@belsonsteel.com
 T: (815)932-7416
 F:



OIL CONDITION

Visc @ 40°C	cSt	153	148	165	86.9
-------------	-----	------------	-----	-----	------



CONTAMINATION

Water	%	NEG	0.097	0.296	NEG
Silicon	ppm	133	58	245	60
Sodium	ppm	2	3	8	3
Potassium	ppm	7	3	15	5



WEAR METALS

Iron	ppm	764	247	912	1189
Copper	ppm	3	2	5	4
Lead	ppm	3	1	6	2
Tin	ppm	<1	0	2	<1
Aluminum	ppm	38	17	73	15
Chromium	ppm	14	3	22	13
Molybdenum	ppm	2	<1	4	2
Nickel	ppm	1	0	1	<1
Titanium	ppm	4	1	7	<1
Silver	ppm	<1	0	0	0
Manganese	ppm	27	8	36	10
Vanadium	ppm	<1	<1	1	<1



ADDITIVES

Calcium	ppm	543	372	2979	105
Magnesium	ppm	78	27	160	21
Zinc	ppm	172	150	908	15
Phosphorus	ppm	1616	1525	835	558
Barium	ppm	0	0	2	0
Boron	ppm	82	47	8	13

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot: BELBOU
Unique No: 10883431
Signed: Don Baldrige
Report Date: 17 Feb 2024



CONSTRUCTION EQUIPMENT



GRAPHS

