



# CONSTRUCTION EQUIPMENT

## SPM621972 VOLVO A25G 752521 - TRANSMISSION (AUTO)



**Sample No:** VCP435669  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** SPM621972



### SAMPLE INFORMATION

Sample Number	VCP435669	---	---	---
Sample Date	13 Dec 2023	---	---	---
Machine Hours	3895	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
 5000 INDUSTRIAL HWY  
 GARY, IN  
 US 46406  
 Contact: DAVE ENG  
 DAVE.ENG@ALTG.COM  
 T: (312)350-2560  
 F:



### OIL CONDITION

Visc @ 40°C	cSt	█ 29.6	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 8	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 3	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 83	---	---	---
Copper	ppm	█ 35	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 17	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	█ 106	---	---	---
Magnesium	ppm	█ 29	---	---	---
Zinc	ppm	█ 117	---	---	---
Phosphorus	ppm	█ 179	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 23	---	---	---

**Depot:** VOLVO8885  
**Unique No:** 10883469  
**Signed:** Don Baldrige  
**Report Date:** 17 Feb 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

