CONSTRUCTION EQUIPMENT SW0-069538 LH0IST VOLVO L350H 1007 - COOLANT



Sample No: VCP444437

VOLVO

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No:

Coolant Color

SWO-069538 LHOIST

Yllow

Sample Number	-	VCP444437	VCP431079	VCP402615	VCP373067
Sample Date		09 Feb 2024	17 Nov 2023	05 Apr 2023	15 Apr 2022
Machine Hours		1802	17555	1551	12518
Sample Status		NORMAL	NORMAL	NORMAL	NORMAL
COOLANT	CONDITION				
рН	Scale 0-14	8.11	7.44	7.66	7.76
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	NT NT	NT	NT	NT
Percentage Glycol	%	42.5	40.4	40.0	46.1
Freezing Point	°C	-17	- 13	- 13	-26
CONTAMIN	ATION				
Coolant Appearance		normal	normal	normal	normal

Yllow

Yllow

Yllow



COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY **BIRMINGHAM, AL** US 35217 Contact: BRANTLY CLAY bclay@cowin.com T: F: (205)856-2106

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO8528 Unique No: 10883546 Signed: Jonathan Hester Report Date: 20 Feb 2024


CONSTRUCTION EQUIPMENT




GRAPHS

Iron/Tin/Silver

VOLVO





Report Id: VOLVO8528 [WUSCAR] 06090693 (Generated: 02/21/2024 17:56:46) Rev: 1