



# CONSTRUCTION EQUIPMENT

## VOLVO A25G 752974 - DROP BOX



**Sample No:** VCP403067

**Oil Type:** {unknown}

**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP403067	---	---	---
Sample Date	14 Feb 2024	---	---	---
Machine Hours	528	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

### ALTA EQUIPMENT COMPANY

5210 REESE ROAD  
DAVIE, FL  
US 33314

Contact: N. FACEY  
nfacey@altaequipfl.com  
T: (954)581-4744  
F: (954)583-0318



### OIL CONDITION

Visc @ 40°C	cSt	█ 49.7	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 7	---	---	---
Potassium	ppm	█ <1	---	---	---



### WEAR METALS

Iron	ppm	█ 65	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 6	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	9	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	40	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	42	---	---	---
Phosphorus	ppm	2435	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	211	---	---	---

### Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0095  
**Unique No:** 10884893  
**Signed:** Don Baldrige  
**Report Date:** 20 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

