

# CONSTRUCTION EQUIPMENT 12034 CLEAN EARTH VOLVO L 180H 4116 - FRONT AXLE

LE

**Sample No:** VCP442339 **Oil Type:** VOLVO WB 101

**Job No:** 12034 CLEAN EARTH

SAMPLE	INFORMATIO	N		
Sample Number		VCP442339	 	
Sample Date		10 Feb 2024	 	
Machine Hours		16600	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>42.0</b>	 	
VOLVO				
CONTAN	MOITAMIN			
Water	%	NEG	 	
Silicon	ppm	■27	 	
Sodium	ppm	<b>9</b>	 	
Potassium	ppm	■0	 	
VOLVO	AFTAL C			
WEAR M	AF I ALS			
Iron	ppm	<u>▲</u> 532	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>1</b>	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	2	 	
Silver	ppm	0	 	
Manganese	ppm	<b>4</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	IEC		 	
	15			
Calcium	ppm	2815	 	
Magnesium	ppm	<b>12</b>	 	
Zinc	ppm	<b>1293</b>	 	
Phosphorus	ppm	<b>1082</b>	 	
Barium	ppm	■0	 	
Boron	ppm	■92	 	



#### **HOFFMAN EQUIPMENT - LIONVILLE**

120 GORDON DRIVE LIONVILLE, PA US 19341 Contact: JIM FEHR jim.fehr@hoffmanequip.com T: (610)363-9200 F: (610)594-0829

### Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO8879

 Unique No:
 10884896

 Signed:
 Don Baldridge

 Report Date:
 20 Feb 2024



## **CONSTRUCTION EQUIPMENT**





