CONSTRUCTION EQUIPMENT X59231 VOLVO A25G 752703 - HYDRAULIC SYSTEM



Sample No:	VCP442709			
Oil Type:	{unknown}			
Job No:	X59231			

**ZOTAZO** 

	FORMATION			
			 	<u>.</u>
Sample Number		VCP442709	 	
Sample Date		12 Feb 2024	 	
Machine Hours		1976	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	<b>43.0</b>	 	
Acid Number (AN)	mg KOH/g	0.767	 	
			 _	
Water	%	NEG	 	
Particles >4µm		5102	 	
Particles >6µm		1271	 	
Particles >14µm		<b>72</b>	 	
ISO 4406:1999 (c)		20/17/13	 	



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087

Contact: DANA FOSHEE dfoshee@scottcompanies.com T: (504)461-0961 F: (504)461-0970

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is ISO 46 AW Hydraulic Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

WEAR I	METALS			
Iron	ppm	<b>4</b>	 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	2	 	
Tin	ppm		 	
Aluminum	ppm	□<1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<1	 	
Vanadium	ppm	0	 	

ADD

Silicon

Sodium

Potassium

1

ppm

ppm

ppm

6

4

0 🔲

	VES			
Calcium	ppm	80	 	
Magnesium	ppm	2	 	
Zinc	ppm	415	 	
Phosphorus	ppm	301	 	
Barium	ppm	<1	 	
Boron	ppm	0	 	

 Depot:
 SCOSAI

 Unique No:
 10885128

 Signed:
 Wes Davis

 Report Date:
 20 Feb 2024

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO

