CONSTRUCTION EQUIPMENT X59231 VOLVO A25G 752703 - FRONT AXLE



 Sample No:
 VCP437139

 Oil Type:
 GEAR OIL SAE 80W90

 Job No:
 X59231

VOLVO

## SAMPLE INFORMATION

Molybdenum

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

ppm

**ADDITIVES** 

	NF UKMA I IUN			
Sample Number		VCP437139	VCP425399	 
Sample Date		12 Feb 2024	16 Nov 2023	 
Machine Hours		1976	1473	 
Oil Hours		0	0	 
Oil Changed		Changed	Changed	 
Sample Status		NORMAL	NORMAL	 
OIL CONDI	TION			
Visc @ 40°C	cSt	143	84.6	 
CONTAMI	NATION		_	
Water	%	NEG	NEG	 
Silicon	ppm	<b>□</b> <1	4	 
Sodium	ppm	0	<b></b> < 1	 
Potassium	ppm	2	2	 
WEAR ME	TALS			
Iron	ppm	62	265	 
Copper	ppm	8	35	 
Lead	ppm	0	0	 
Tin	ppm	0	2	 
Aluminum	ppm	2	<b></b> <1	 
Changensterne		- 4		
Chromium	ppm	∎<1	5	 

4

0

0

0

10

800

361

1364

3

7 216

□3



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997

SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	SCOSAI
Unique No:	10885418
Signed:	Don Baldridge
Report Date	: 20 Feb 2024

**||** <1

0

0

0

137

**||** <1

55 🔲

0 🔲

1133

189

1

0


Contact/Location: DENISE CORVERS - SCOSAI

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: SCOSAI [WUSCAR] 06092565 (Generated: 02/20/2024 23:01:15) Rev: 1

Contact/Location: DENISE CORVERS - SCOSAI