



# CONSTRUCTION EQUIPMENT

660716 CITY LAKELAND VOLVO L60H 62235 - FRONT AXLE



**Sample No:** VCP432116  
**Oil Type:** VOLVO WB 102  
**Job No:** 660716 CITY LAKELAND



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
 8418 PALM RIVER ROAD  
 TAMPA, FL  
 US 33619  
 Contact: KENNY HANEY  
 khaney@flaglerce.com  
 T: (813)630-0077  
 F: (813)630-2233



## SAMPLE INFORMATION

Sample Number	<b>VCP432116</b>	VCP392913	---	---
Sample Date	<b>22 Jan 2024</b>	12 Jan 2023	---	---
Machine Hours	<b>1925</b>	1354	---	---
Oil Hours	<b>1925</b>	1354	---	---
Oil Changed	<b>Changed</b>	Not Chngd	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---



## OIL CONDITION

Visc @ 40°C	cSt	<b>39.8</b>	39.9	---	---
-------------	-----	-------------	------	-----	-----



## CONTAMINATION

Water	%	<b>NEG</b>	NEG	---	---
Silicon	ppm	<b>13</b>	14	---	---
Sodium	ppm	<b>7</b>	10	---	---
Potassium	ppm	<b>4</b>	2	---	---



## WEAR METALS

Iron	ppm	<b>109</b>	93	---	---
Copper	ppm	<b>3</b>	2	---	---
Lead	ppm	<b>0</b>	<1	---	---
Tin	ppm	<b>0</b>	<1	---	---
Aluminum	ppm	<b>2</b>	1	---	---
Chromium	ppm	<b>4</b>	4	---	---
Molybdenum	ppm	<b>3</b>	4	---	---
Nickel	ppm	<b>&lt;1</b>	0	---	---
Titanium	ppm	<b>&lt;1</b>	0	---	---
Silver	ppm	<b>0</b>	0	---	---
Manganese	ppm	<b>7</b>	7	---	---
Vanadium	ppm	<b>0</b>	0	---	---



## ADDITIVES

Calcium	ppm	<b>3700</b>	3788	---	---
Magnesium	ppm	<b>10</b>	13	---	---
Zinc	ppm	<b>1593</b>	1582	---	---
Phosphorus	ppm	<b>1322</b>	1205	---	---
Barium	ppm	<b>10</b>	0	---	---
Boron	ppm	<b>116</b>	128	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0093  
**Unique No:** 10886636  
**Signed:** Wes Davis  
**Report Date:** 21 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

