



CONSTRUCTION EQUIPMENT

662078 VOLVO A30F 82303 - COOLANT



Sample No: VCP432047
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 662078



SAMPLE INFORMATION

Sample Number	VCP432047	---	---	---
Sample Date	02 Feb 2024	---	---	---
Machine Hours	12787	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.68	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 48.5	---	---	---
Freezing Point	°C	■ -31	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

RIPA AND ASSOCIATES

10149 FISHER AVENUE
TAMPA, FL
US 33619
Contact: PM Services
PMServices@ripaconstruction.com
T:
F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: RIPTAM
Unique No: 10887516
Signed: Doug Bogart
Report Date: 22 Feb 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

