



# CONSTRUCTION EQUIPMENT

SW-29950 SEG 1 RANGO VOLVO R100E 121011 - LEFT BRAKE



**Sample No:** VCP372328  
**Oil Type:** {unknown}  
**Job No:** SW-29950 SEG 1 RANGO



## SAMPLE INFORMATION

Sample Number	VCP372328	---	---	---
Sample Date	16 Feb 2024	---	---	---
Machine Hours	7877	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ARNOLD MACHINERY COMPANY**  
 2975 WEST 2100 SOUTH  
 SALT LAKE CITY, UT  
 US 84119  
 Contact: TJ LARK  
 tlark@arnoldmachinery.com  
 T: (801)972-4000  
 F: (801)975-9434



## OIL CONDITION

Visc @ 40°C	cSt	■ 73.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 19	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 0	---	---	---



## WEAR METALS

Iron	ppm	■ 8	---	---	---
Copper	ppm	■ 83	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	1982	---	---	---
Magnesium	ppm	10	---	---	---
Zinc	ppm	725	---	---	---
Phosphorus	ppm	648	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO8770  
**Unique No:** 10896959  
**Signed:** Don Baldrige  
**Report Date:** 26 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

