

CONSTRUCTION EQUIPMENT
74854 LAKE CONWAY TAKEUCHI TB230R 130008591 - REAR LEI

Sample No: VCP445693

Oil Type: **GEAR OIL SAE 80W90** Job No: 74854 LAKE CONWAY

VOLVO	INFORMATIO	N		
	INFORMATIO			
Sample Number		VCP445693	 	
Sample Date		19 Feb 2024	 	
Machine Hours		1006	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	= 207	 	
VISC @ 40°C	CST	<b>207</b>	 	
VOLVO				
CONTAN	INATION			
Water	%	NEG	 	
Silicon	ppm	<u> </u>	 	
Sodium	ppm	<b>7</b>	 	
Potassium	ppm	<b>■&lt;1</b>	 	
	PP			
VOLVO				
WEAR M	IETALS			
Iron	ppm	<u> </u>	 	
Copper	ppm	<b>4</b>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	<b>■</b> 0	 	
Aluminum	ppm	<b>6</b>	 	
Chromium	ppm	<u>^</u> 25	 	
Molybdenum	ppm	<b>3</b>	 	
Nickel	ppm	<b>5</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>1</b> 6	 	
Vanadium	ppm	0	 	
ADDITIV	/FS			
	_	= 10F		
Calcium	ppm	<b>105</b>	 	
Magnesium	ppm	<b>22</b>	 	
Zinc	ppm	<b>208</b>	 	
Phosphorus	ppm	<b>□</b> 751	 	
Barium	ppm	<b>18</b>	 	
Boron	ppm	<b>108</b>	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other metal levels are typical for a new component breaking in. Elemental level of silicon (Si) above normal indicating ingress of seal material. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093 **Unique No:** 10896986 Signed: Don Baldridge Report Date: 26 Feb 2024



## **CONSTRUCTION EQUIPMENT**





