



# CONSTRUCTION EQUIPMENT

674850 LAKE CONWAY TAKEUCHI TL8 408004880 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP443262  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 674850 LAKE CONWAY



## SAMPLE INFORMATION

Sample Number	VCP443262	VCP398539	---	---
Sample Date	19 Feb 2024	03 Feb 2023	---	---
Machine Hours	380	32	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Not Chngd	---	---
Sample Status	ABNORMAL	NORMAL	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: ANDREW MCCOY  
 amccoy@flaglerce.com  
 T:  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█ 163	█ 159	---	---
-------------	-----	-------	-------	-----	-----



## CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	█ 22	█ 12	---	---
Sodium	ppm	█ 5	█ 4	---	---
Potassium	ppm	█ 2	█ 2	---	---



## WEAR METALS

Iron	ppm	▲ 1077	█ 466	---	---
Copper	ppm	█ 2	█ 1	---	---
Lead	ppm	█ 0	█ 0	---	---
Tin	ppm	█ 0	█ <1	---	---
Aluminum	ppm	█ 0	█ <1	---	---
Chromium	ppm	▲ 11	█ 8	---	---
Molybdenum	ppm	█ 0	█ <1	---	---
Nickel	ppm	█ <1	█ <1	---	---
Titanium	ppm	0	<1	---	---
Silver	ppm	0	0	---	---
Manganese	ppm	█ 14	█ 8	---	---
Vanadium	ppm	0	0	---	---



## ADDITIVES

Calcium	ppm	█ 48	█ 9	---	---
Magnesium	ppm	█ 0	█ <1	---	---
Zinc	ppm	█ 49	█ 21	---	---
Phosphorus	ppm	█ 241	█ 310	---	---
Barium	ppm	█ 10	█ 12	---	---
Boron	ppm	█ <1	█ 0	---	---

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 10896989  
**Signed:** Don Baldrige  
**Report Date:** 26 Feb 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

