



CONSTRUCTION EQUIPMENT

VOLVO A30G 12345 - 2 GEARBOX



Sample No: VCP439114

Oil Type: IMONZA

Job No:



SAMPLE INFORMATION

Sample Number	VCP439114	---	---	---
Sample Date	21 Feb 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: BRAD BYRO
 bradley.byro@altg.com
 T: (407)850-9614
 F: (407)659-8720



OIL CONDITION

Visc @ 40°C	cSt	█ 113	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ <1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ <1	---	---	---
Copper	ppm	█ 0	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	51	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	929	---	---	---
Magnesium	ppm	876	---	---	---
Zinc	ppm	1100	---	---	---
Phosphorus	ppm	916	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	1	---	---	---

Depot: VOLVO0096
Unique No: 10896992
Signed: Don Baldrige
Report Date: 26 Feb 2024




CONSTRUCTION EQUIPMENT



GRAPHS

Iron (ppm)




Lead (ppm)



Aluminum (ppm)




Chromium (ppm)



Copper (ppm)



Silicon (ppm)



Viscosity @ 40°C



Additives

