



CONSTRUCTION EQUIPMENT

674462 MOSAIC VOLVO L110H 12152 - COOLANT



Sample No: VCP441889
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 674462 MOSAIC



SAMPLE INFORMATION

Sample Number	VCP441889	---	---	---
Sample Date	16 Feb 2024	---	---	---
Machine Hours	6265	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233



COOLANT CONDITION

pH	Scale 0-14	■ 7.44	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 47.6	---	---	---
Freezing Point	°C	■ -28	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

Depot: VOLVO0093
Unique No: 10897067
Signed: Jonathan Hester
Report Date: 28 Feb 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

