



CONSTRUCTION EQUIPMENT

433891 PATRICK OHMST VOLVO SD25D 194145 - COOLANT



Sample No: VCP368539
Oil Type: VOLVO COOLANT (GREEN)
Job No: 433891 PATRICK OHMST



SAMPLE INFORMATION

Sample Number	VCP368539	---	---	---
Sample Date	11 Dec 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	ABNORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 8.69	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 560	---	---	---
Percentage Glycol	%	■ 55.3	---	---	---
Freezing Point	°C	■ -47	---	---	---



CONTAMINATION

Coolant Appearance	▲ sediment	---	---	---
Coolant Color	Yellow	---	---	---

ALTA EQUIPMENT

5985 COURT STREET ROAD
SYRACUSE, NY
US 13206

Contact: JIM STRIGLE
JIM.STRIGLE@ALTG.COM

T: (315)437-2611
F: (315)434-9471

Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Sediment present. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0142
Unique No: 10897070
Signed: Jonathan Hester
Report Date: 28 Feb 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

