

CONSTRUCTION EQUIPMENT VOLVO A40G 353407 - FRONT AXLE



Sample No: VCP416818

Oil Type: MOBIL MOBILUBE HD 80W90

Job No:

CAMPLE	INFORMATION				
Sample Number		VCP416818	VCP341891	VCP312574	
Sample Date		25 Feb 2024	14 Dec 2023	03 Oct 2023	
Machine Hours		1268	997	504	
Oil Hours		871	600	504	
Oil Changed		Changed	Not Changd	Not Changd	
Sample Status		ATTENTION	ATTENTION	ATTENTION	
Sample Status		ATTENTION	ATTENTION	ATTENTION	
VOLVO					
OIL CON	DITION				
Visc @ 40°C	cSt	▲ 52.3	▲ 52.0	▲ 52.3	
VOLVO					
_	<u>IINATION</u>				
Water	%	NEG	NEG	NEG	
Silicon	ppm	■2	2	3	
Sodium	ppm	■2	 <1	0	
Potassium	ppm	■ 5	4	5	
WEAR M	IFTAI S				
		=4.42	7454	=400	
Iron	ppm	143	154	129	
Copper	ppm	2	0	1	
Lead	ppm	- <1	0	0	
Tin	ppm		0	0	
Aluminum	ppm	■ <1	0	1	
Chromium	ppm	1	2	2	
Molybdenum	ppm	■3	1	3	
Nickel	ppm		0	- <1	
Titanium	ppm	0	0	0	
Silver	ppm	0	0	0	
Manganese	ppm	6	7	6	
Vanadium	ppm	0	0	0	
VOLVO					
ADDITIV	ES				
Calcium	-	1 5	1 6		
Magnesium	ppm	1 3	0	■ 12 ■ <1	
Zinc	ppm	3	1 6	□ 0	
Phosphorus	ppm	2197	2220	□ 0 □ 2284	
Barium	ppm	0			
	ppm		0	0	
Boron	ppm	241	■234	■286	



SCHILDBERG CONSTRUCTION COMPANY

PO BOX 358 GREENFIELD, IA US 50849 Contact: SCOTT ARMSTRONG sarmstrong@schildberg.com T: (641)743-8237 F: (641)743-2486

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot:SCHGREUnique No:10898652Signed:Jonathan HesterReport Date:28 Feb 2024



CONSTRUCTION EQUIPMENT





