



CONSTRUCTION EQUIPMENT

VOLVO A40G 352351 - FRONT AXLE



Sample No: VCP416814
Oil Type: MOBIL MOBILUBE HD 80W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP416814	VCP339707	VCP406106	VCP384397
Sample Date	13 Feb 2024	07 Nov 2023	24 Aug 2023	30 May 2023
Machine Hours	8269	7750	7188	6612
Oil Hours	1081	562	1168	592
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	ABNORMAL	NORMAL	ABNORMAL

SCHILDBERG CONSTRUCTION COMPANY
 PO BOX 358
 GREENFIELD, IA
 US 50849
 Contact: SCOTT ARMSTRONG
 sarmstrong@schildberg.com
 T: (641)743-8237
 F: (641)743-2486



OIL CONDITION

Visc @ 40°C	cSt	139	138	138	142
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	3	2	4	2
Sodium	ppm	<1	<1	0	<1
Potassium	ppm	1	0	<1	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	16	35	15	10
Copper	ppm	<1	0	0	0
Lead	ppm	<1	0	0	0
Tin	ppm	<1	0	0	0
Aluminum	ppm	<1	0	0	0
Chromium	ppm	0	0	<1	0
Molybdenum	ppm	1	<1	<1	1
Nickel	ppm	<1	0	0	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	199	192	143	132
Magnesium	ppm	10	4	14	13
Zinc	ppm	78	83	50	56
Phosphorus	ppm	984	1000	1017	1023
Barium	ppm	0	0	0	0
Boron	ppm	171	171	228	209

Depot: SCHGRE
Unique No: 10898653
Signed: Wes Davis
Report Date: 27 Feb 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

