

# CONSTRUCTION EQUIPMENT 390585 CUMMINS G090019362 - COOLANT



Sample No: VCP306496

Oil Type: HYBRID (HOAT) COOLANT

**Job No:** 390585

CAMDI F II	FORMATION				
	II UMPIATION		<u></u>		
Sample Number		VCP306496			
Sample Date		21 Feb 2024			
Machine Hours		1200			
Sample Status		NORMAL			
COOLANT CONDITION					
LUULANI	LUNDITIUM				
рН	Scale 0-14	<b>9.57</b>			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	<b>2516</b>			
Percentage Glycol	%	<b>■53.1</b>			
Freezing Point	°C	<b>-43</b>			
CONTAMIN	IATION				
CONTAMIN	ATIUN				
Coolant Appearance		normal			
Coolant Color		Yllow			

#### AJAX ENTERPRISES OF MICHIGAN LLC

830 KIRTS TROY, MI US 48084

Contact: SERVICE MANAGER

T: (248)244-3300

F:

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

Depot:AJATROUnique No:10898850Signed:Jonathan HesterReport Date:28 Feb 2024



# **CONSTRUCTION EQUIPMENT**





### **GRAPHS**

