
CONSTRUCTION EQUIPMENT SPM674034

SENNEBOGEN 835E 835.0.3239 - REAR RIGHT FINAL D

Sample No:	VCP429204		
Oil Type:	GEAR OIL SAE 80W90		
Job No:	SPM674034		

VOLVO

SAMPLE INFORMATION VCP429204 Sample Number Sample Date 15 Feb 2024 Machine Hours 991 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 138 CONTAMINATION Water % NEG Silicon ppm 5 Sodium 6 🔲 ppm Potassium ppm ■ <1 OL WEAR METALS 103 Iron ppm Copper ppm 58 Lead ppm 0 🔲 Tin ppm 0 Aluminum ppm ■<1



ADDITI	VES			
Calcium	ppm	1 0	 	
Magnesium	ppm	3	 	
Zinc	ppm	36	 	
Phosphorus	ppm	1839	 	
Barium	ppm	5	 	
Boron	ppm	131	 	



BELSON STEEL

1685 N STATE RTE 50 BOURBONNAIS, IL US 60914 Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: BELBOU Unique No: 10900219 Signed: Jonathan Hester **Report Date:** 29 Feb 2024


Contact/Location: M. POZAN - BELBOU

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: BELBOU [WUSCAR] 06101989 (Generated: 02/29/2024 14:48:01) Rev: 1

Contact/Location: M. POZAN - BELBOU