

## **CONSTRUCTION EQUIPMENT**

SPM674034 SENNEBOGEN 835E 835.0.3239 - FRONT LEFT FINAL

Sample No: VCP429208

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SPM674034

SAMPLI	E INFORMATION			
Sample Number		VCP429208	 	
Sample Date		15 Feb 2024	 	
Machine Hours		991	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		SEVERE	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>138</b>	 	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>■</b> 3	 	
Sodium	ppm	<b>10</b>	 	
Potassium	ppm	<b>2</b>	 	
WEAR N	METALC			
_				
Iron	ppm	■331	 	
Copper	ppm	<b>439</b>	 	
Lead	ppm	<b>   &lt;1</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	■10	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>15</b>	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	<b>18</b>	 	
Magnesium	ррт	<b>2</b>	 	
Zinc	ppm	<b>□2</b> 292	 	
Phosphorus	ppm	■1802	 	
Barium	ppm	<b>4</b>	 	
Boron	ppm	■81	 	
50.011	PPIII			



#### BELSON STEEL 1685 N STATE RTE 50 BOURBONNAIS, IL US 60914

Contact: M. POZAN mpozan@belsonsteel.com T: (815)932-7416

F:

### Diagnosis

The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. The copper level is severe. Moderate concentration of visible metal present. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:BELBOUUnique No:10900225Signed:Jonathan HesterReport Date:29 Feb 2024

Contact/Location: M. POZAN - BELBOU



# **CONSTRUCTION EQUIPMENT**





#### **GRAPHS**

