



CONSTRUCTION EQUIPMENT

675223 COCOA VOLVO G930C 675223 - TRANSMISSION (AUTO)



Sample No: VCP438813
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 675223 COCOA



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



SAMPLE INFORMATION

Sample Number	VCP438813	---	---	---
Sample Date	22 Feb 2024	---	---	---
Machine Hours	951	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 28.83	---	---	---
-------------	-----	---------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 27	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ 2	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 161	---	---	---
Magnesium	ppm	█ 13	---	---	---
Zinc	ppm	█ 114	---	---	---
Phosphorus	ppm	█ 199	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	34	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0096
Unique No: 10900326
Signed: Wes Davis
Report Date: 04 Mar 2024



CONSTRUCTION EQUIPMENT



GRAPHS

