

CONSTRUCTION EQUIPMENT VOLVO L60H 621313 - TRANSMISSION (AUTO)



TALA

Sample No: VCP438435

VOLVO AUTOMATIC TRANSMISSION FLUID AT102

Oil Type: Job No:

VOLVO						
	E INFORMATION		-			the second se
Sample Number		VCP438435				
Sample Date		23 Feb 2024				SOUTH FLORIDA EXCAVATION
Machine Hours		10386				1455 RAIL HEAD BLVD STE 3
Oil Hours		0				NAPLES, FL
Oil Changed		Not Changd				US 34110-8407
Sample Status		NORMAL				Contact: ROB ANDERSON
						CHOOEH@EMBARQMAILCOM;KI_GERRARD@YAHOO.COM;ROBDIGSDIRT@AOLCOM
OIL CON	NDITION					T: (239)596-8111
Visc @ 40°C	cSt	28.9				F: (239)596-8112
	CSC	20.5				
VOLVO						Diagnosis
CONTA	MINATION	Resample at the next service interval				
Water	%	NEG				to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable
Silicon	ppm	9				
Sodium	ppm	6				
Potassium	ppm	4				
						for the time in service.
VOLVO	METALC					
WEAK	METALS					
Iron	ppm	35				
Copper	ppm	1 4				
Lead	ppm	 <1				
Tin	ppm	■<1				
Aluminum	ppm	 <1				
Chromium	ppm					
Molybdenum	ppm	 <1				
Nickel	ppm					
Titanium	ppm	<1				
Silver	ppm	0				
Manganese	ppm	4				
Vanadium	ppm	<1				
	VFS					
			<u>.</u>			
Calcium	ppm	180				
Magnesium	ppm	4				
Zinc	ppm	49				
Phosphorus	ppm	371				
Barium	ppm	2				
Boron	ppm	109				

 Depot:
 SOUNAPFL

 Unique No:
 10900331

 Signed:
 Wes Davis

 Report Date:
 28 Feb 2024


Contact/Location: ROB ANDERSON - SOUNAPFL

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: SOUNAPFL [WUSCAR] 06102101 (Generated: 02/28/2024 13:21:45) Rev: 1

Contact/Location: ROB ANDERSON - SOUNAPFL