CONSTRUCTION EQUIPMENT X59249 VOLVO L220H 003442 - COOLANT



Sample No: VCP424806

Coolant Appearance

Coolant Color

VOLVO

| Oil Type: | VOLVO COOLANT VCS (YELLOW) |
|-----------|----------------------------|
| Job No: | X59249 |

| | NFORMATION | | | | | |
|--------------------|------------|-------------|-------------|--|--|--|
| Sample Number | | VCP424806 | VCP384339 | | | |
| Sample Date | | 19 Feb 2024 | 30 Mar 2023 | | | |
| Machine Hours | | 5968 | 2097 | | | |
| Sample Status | | NORMAL | NORMAL | | | |
| | | | | | | |
| COOLANT | CONDITION | | | | | |
| рН | Scale 0-14 | 7.24 | 8.01 | | | |
| Reserve Alkalinity | Scale 0-20 | | | | | |
| Nitrites | ppm | NT | 0 | | | |
| Percentage Glycol | % | 47.0 | 45.4 | | | |
| Freezing Point | °C | -28 | -24 | | | |
| CONTAMINATION | | | | | | |

normal

Yllow

normal

Yllow



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961 F: (504)461-0970

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:SCOSAIUnique No:10900440Signed:Jonathan HesterReport Date:01 Mar 2024

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

