

# CONSTRUCTION EQUIPMENT VOLVO L90H 625035 - FRONT AXLE



Sample No: VCP444261

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No:

CVMDIE	E INFORMATIO	V		
	INFURMATIU	<u>.</u>		
Sample Number		VCP444261	VCP395993	 
Sample Date		15 Feb 2024	30 Jan 2023	 
Machine Hours		3984	3010	 
Oil Hours		0	1000	 
Oil Changed		Changed	Not Changd	 
Sample Status		NORMAL	NORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>47.2</b>	<b>47.7</b>	 
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	 
Silicon	ppm	■20	<b>2</b> 1	 
Sodium	ppm	<b>4</b>	<b>3</b>	 
Potassium	ppm	<1	0	 
	P   S			
VOLVO	AETAL C			
WEAR N	NE I ALS			
Iron	ppm	<b>78</b>	<b>□</b> 64	 
Copper	ppm	<b>0</b>	<b>-</b> <1	 
Lead	ppm	<b>1</b>	<b>1</b>	 
Tin	ppm	<b>-&lt;1</b>	<b>-</b> <1	 
Aluminum	ppm	<b>1</b>	< 1	 
Chromium	ppm	<b>2</b>	_2	 
Molybdenum	ppm	<b>■</b> 3	<b>4</b>	 
Nickel	ppm	<b>0</b>	<b>-</b> <1	 
Titanium	ppm	■0	<1	 
Silver	ppm	0	3	 
Manganese	ppm	<b>5</b>	<b>5</b>	 
Vanadium	ppm	0	0	 
ADDITIV	VES			
Calcium	ppm	■3516	■3969	 
Magnesium	ppm	<b>11</b>	<b>1</b> 9	 
Zinc	ppm	<b>1338</b>	■1527	 
Phosphorus	ppm	<b>1195</b>	<b>1172</b>	 
Barium	ppm	<b>0</b>	<b>0</b>	 
Boron	ppm	<b>121</b>	<b>138</b>	 



#### **RIPA AND ASSOCIATES**

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:RIPTAMUnique No:10900833Signed:Don BaldridgeReport Date:29 Feb 2024



## **CONSTRUCTION EQUIPMENT**





#### GRAPHS

