

## **CONSTRUCTION EQUIPMENT**

RIOR VOLVO A30G 753239 - TRANSMISSION (AUTO)

Sample No: VCP441532

Oil Type: DIESEL ENGINE OIL SAE 15W40

Job No: SUPERIOR

VOLVO	INCORMATION			
	INFORMATION			
Sample Number		VCP441532	VCP386695	 
Sample Date		17 Feb 2024	19 Sep 2023	 
Machine Hours		1261	610	 
Oil Hours		0	0	 
Oil Changed		N/A	Not Changd	 
Sample Status		ABNORMAL	ABNORMAL	 
OIL CON	DITION			
Visc @ 40°C	cSt	33.9	■31.6	 
VOLVO				
CONTAM	IINATION			
Water	%	NEG	NEG	 
Silicon	ppm	<b>14</b>	<b>1</b> 4	 
Sodium	ppm	7	2	 
Potassium	ppm	<b>4</b>	<b>6</b> 0	 
		_		
VOLVO	IETAL C			
WEAR M	IF I ALS			
Iron	ppm	■27	■22	 
Copper	ppm	■20	<b>1</b> 6	 
Lead	ppm	<b>1</b>	< 1	 
Tin	ppm	<b>■</b> 3	2	 
Aluminum	ppm	<b>18</b>	<b>1</b> 0	 
Chromium	ppm	■0	0	 
Molybdenum	ppm	<b>0</b>	<b>-</b> <1	 
Nickel	ppm	<b>■&lt;1</b>	2	 
Titanium	ppm	■0	0	 
Silver	ppm	■0	0	 
Manganese	ppm	<b>4</b>	<b>3</b>	 
Vanadium	ppm	0	0	 
ADDITIV	ES			
Calcium	ppm	<b>61</b>	<b>7</b> 5	 
Magnesium	ppm	<b>■</b> <1	<b>-</b> <1	 
Zinc	ppm	<b>■</b> 3	<b>5</b>	 
Phosphorus	ppm	<b>174</b>	■195	 
Barium	ppm	<b>-&lt;1</b>	<b>0</b>	 
Boron	ppm	<b>73</b>	<b>113</b>	 



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the fluid. The fluid viscosity is lower than normal. Additive levels indicate the addition of a different brand, or type of fluid. Confirm oil type.

 Depot:
 VOLVO0093

 Unique No:
 10900857

 Signed:
 Don Baldridge

 Report Date:
 29 Feb 2024



## **CONSTRUCTION EQUIPMENT**





