

CONSTRUCTION EQUIPMENT

661880 MOSAIC VOLVO EC480EL 315030 - HYDRAULIC SYSTEM

Sample No: VCP452271

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No: 661880 MOSAIC

CAMPI F IN	FORMATION				
	II OMPATION		140040000	_	_
Sample Number		VCP452271	VCP426239		
Sample Date		31 Jan 2024	29 Sep 2023		
Machine Hours		1027	584		
Oil Hours		1027	584		
Oil Changed		Not Changd	Not Changd		
Sample Status		NORMAL	ATTENTION		
OIT CONDI	TION				
Visc @ 40°C	cSt	42.1	42.4		
Acid Number (AN)	mg KOH/g	■ 1.01	■ 0.51		
CONTAMINATION					
	·			-	-

CONTAMINATION						
Water	%	NEG	NEG			
Particles >4µm		■ 5485	42172			
Particles >6µm		■393	6268			
Particles > 14µm		21	128			
ISO 4406:1999 (c	:)	20/16/12	23/20/14			
Silicon	ppm	6	5			
Sodium	ppm	2	1			
Potassium	ppm	1	2			

VOLVO	AETAL C			
WEAR N	JE I ALS			
Iron	ppm	■2	□0	
Copper	ppm	17	1 3	
Lead	ppm	■<1	1	
Tin	ppm	■0	 <1	
Aluminum	ppm	■<1	< 1	
Chromium	ppm	■ 0	0	
Molybdenum	ppm	■0	■0	
Nickel	ppm	■<1	 <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	■<1	< 1	
Vanadium	ppm	0	0	

ADDITI	IVES			
Calcium	ppm	■84	■92	
Magnesium	ppm	■1	4	
Zinc	ppm	556	605	
Phosphorus	ppm	408	439	
Barium	ppm	0	■0	
Boron	ppm	■ 0	■0	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: JOHN FARDELLA
john.fardella@altg.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0093

 Unique No:
 10901138

 Signed:
 Wes Davis

 Report Date:
 29 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPHS

