



CONSTRUCTION EQUIPMENT

673784 SENNEBOGEN 840 2364 - REAR AXLE



Sample No: VCP442447
Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No: 673784



SAMPLE INFORMATION

Sample Number	VCP442447	---	---	---
Sample Date	20 Feb 2024	---	---	---
Machine Hours	3131	---	---	---
Oil Hours	1131	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE
 DETROIT, MI
 US 48207

Contact: KEITH HALL
 keith.hall@fpt1.com

T:
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 175	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 11	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 52	---	---	---
Copper	ppm	█ 15	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 14	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 18	---	---	---
Phosphorus	ppm	█ 1317	---	---	---
Barium	ppm	█ 335	---	---	---
Boron	ppm	█ 34	---	---	---

Depot: FERDET
Unique No: 10901594
Signed: Sean Felton
Report Date: 01 Mar 2024



CONSTRUCTION EQUIPMENT



GRAPHS

