

CONSTRUCTION EQUIPMENT VOLVO L 150H 6989 - FRONT AXLE



Sample No: VCP432598
Oil Type: VALVOLINE

Job No:

SAMPL	E INFORMATION				
Sample Number	•	VCP432598	VCP407071	VCP411568	
Sample Date		22 Feb 2024	15 Dec 2023	02 Oct 2023	
Machine Hours		6479	5961	5387	
Oil Hours		0	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		ABNORMAL	ABNORMAL	NORMAL	
VOLVO	IDITION				
OIL CON					
Visc @ 40°C	cSt	44.9	44.3	□ 56.6	
VOLVO					
CONTAI	MINATION				
Water	%	NEG	NEG	NEG	
Silicon		NEG ■ 15	14	INEG	
Sodium	ppm	3	1 4	3	
Potassium		0	<1	2	
Fotassium	ppm				
VOLVO					
WEAR I	METALS				
Iron	ppm	1 9	2 3	4 3	
Copper	ppm	■<1	0		
Lead	ppm	-<1	0		
Tin	ppm	■ 0	- <1	■0	
Aluminum	ppm	2	1	0	
Chromium	ppm	■<1	- <1	1	
Molybdenum	ppm	0	0	2	
Nickel	ppm	■ 0	- <1	- <1	
Titanium	ppm	0	<1	<1	
Silver	ppm	0	0	0	
Manganese	ppm	1	<1	■3	
Vanadium	ppm	0	<1	0	
ADDITI	VES				
Calcium	ppm	3693	4007	□3236	
Magnesium	ppm	17	21	1 11	
Zinc	ppm	1541	1669	□ 1324	
Phosphorus	ppm	1278	1397	1198	
Barium	ppm	0	0	1	
Boron	ppm	120	125	□124	
20.011	PPIII	120	123		



CITY CARTING

221 OLD GATE LN MILFORD, CT US 06460 Contact: TAVINS BANKS tavins@citycart.net T: (203)223-3885 F:

Diagnosis

Oil and filter change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:CITMILCONUnique No:10902870Signed:Sean FeltonReport Date:04 Mar 2024



CONSTRUCTION EQUIPMENT





GRAPHS

