



# CONSTRUCTION EQUIPMENT

## VOLVO L90H 625464 - FRONT AXLE



**Sample No:** VCP416566  
**Oil Type:** CHEVRON 1000 THF  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP416566	---	---	---
Sample Date	16 Feb 2024	---	---	---
Machine Hours	4331	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**IAA - INSURANCE AUTO AUCTIONS - DONNA**  
 900 N HUTTO RD  
 DONNA, TX  
 US 78537  
 Contact: DOLLY SANDOVAL  
 YSANDOVAL@IAAI.COM  
 T: (404)275-6868  
 F: (404)366-1011



### OIL CONDITION

Visc @ 40°C	cSt	█ 45.3	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 42	---	---	---
Copper	ppm	█ 40	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 2726	---	---	---
Magnesium	ppm	█ 12	---	---	---
Zinc	ppm	█ 1203	---	---	---
Phosphorus	ppm	█ 1030	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 44	---	---	---

**Depot:** INSDON  
**Unique No:** 10909948  
**Signed:** Wes Davis  
**Report Date:** 04 Mar 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

