



CONSTRUCTION EQUIPMENT

SPM675617 MCIRON VOLVO A45GFS 353666 - TRANSMISSION (AUTO)



Sample No: VCP444422
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: SPM675617 MCIRON



SAMPLE INFORMATION

Sample Number	VCP444422	---	---	---
Sample Date	09 Mar 2024	---	---	---
Machine Hours	1075	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA CONSTRUCTION EQUIPMENT
613 E STEVENSON RD
OTTAWA, IL
US 61350
Contact: KEVIN SKRTICH
KEVIN.SKRTICH@ALTAEQUIPMENT.COM
T:
F:



OIL CONDITION

Visc @ 40°C	cSt	■ 31.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 15	---	---	---
Sodium	ppm	■ 4	---	---	---
Potassium	ppm	■ <1	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the component. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	■ 46	---	---	---
Copper	ppm	■ 44	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 3	---	---	---
Aluminum	ppm	■ 18	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ 5	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	■ 68	---	---	---
Magnesium	ppm	■ 0	---	---	---
Zinc	ppm	■ 2	---	---	---
Phosphorus	ppm	■ 155	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 71	---	---	---

Depot: VOLVO5055
Unique No: 10930057
Signed: Don Baldrige
Report Date: 20 Mar 2024



CONSTRUCTION EQUIPMENT



GRAPHS

