



# CONSTRUCTION EQUIPMENT

687940 ATLAS ORG VOLVO L70 624147 - REAR AXLE



**Sample No:** VCP441511  
**Oil Type:** VOLVO WET BRAKE TRANSAXLE OIL  
**Job No:** 687940 ATLAS ORG



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
9601 BOGGY CREEK RD  
ORLANDO, FL  
US 32824  
Contact: Robert LaPlante  
robert.laplante@altg.com  
T: (407)508-9736  
F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP441511	---	---	---
Sample Date	13 Mar 2024	---	---	---
Machine Hours	5718	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 50.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 18	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 3	---	---	---



## WEAR METALS

Iron	ppm	█ 178	---	---	---
Copper	ppm	█ 25	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 4	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ 5	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	█ 2736	---	---	---
Magnesium	ppm	█ 19	---	---	---
Zinc	ppm	█ 1191	---	---	---
Phosphorus	ppm	█ 983	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 21	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 10938167  
**Signed:** Don Baldrige  
**Report Date:** 22 Mar 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

