

CONSTRUCTION EQUIPMENT VOLVO A40G 752009 - BOGIE/CENTER AXLE



Sample No: VCP393240

Oil Type: MOBIL MOBILUBE HD 80W90

Job No:

SAMPLE	INFORMATION				
Sample Number		VCP393240	VCP445744	VCP312957	
Sample Date		12 Mar 2024	29 Nov 2023	12 Sep 2023	
Machine Hours		1479	987	482	
Oil Hours		1052	560	482	
Oil Changed		Changed	Not Changd	Not Changd	
Sample Status		NORMAL	NORMAL	NORMAL	
OIL CON	NITION				
		104	104	104	
Visc @ 40°C	cSt	104	104	104	
VOLVO					
CONTAN	INATION				
Water	%	NEG	NEG	NEG	
Silicon	ppm	5	4	4	
Sodium	ppm	 <1	<u></u> <1	<u></u> <1	
Potassium	ppm	5	0	■4	
WEAR N	IETAL C				
_	IC I ALS				
Iron	ppm	■268	■225	■ 148	
Copper	ppm	■3	2	2	
Lead	ppm		0	0	
Tin	ppm	■ <1	0	0	
Aluminum	ppm	2	0	0	
Chromium	ppm	4	3	2	
Molybdenum	ppm	10	9	7	
Nickel	ppm	2		<1	
Titanium	ppm	<1	<1	0	
Silver	ppm	0	0	0	
Manganese	ppm	1 0	9	8	
Vanadium	ppm	<1	<1	0	
VOLVO					
ADDITIV	ES				
Calcium	ppm	140	122	1 53	
Magnesium	ppm	_ 1	0	1	
Zinc	ppm	60	■38	1 70	
Phosphorus	ppm	1203	1348	■1371	
Barium	ppm	2	0	0	
Boron	ppm	■282	■342	■339	



SCHILDBERG CONSTRUCTION COMPANY

PO BOX 358 GREENFIELD, IA US 50849 Contact: SCOTT ARMSTRONG sarmstrong@schildberg.com T: (641)743-8237 F: (641)743-2486

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCHGREUnique No:10938222Signed:Don BaldridgeReport Date:22 Mar 2024



CONSTRUCTION EQUIPMENT





