

## CONSTRUCTION EQUIPMENT T AND K VOLVO A45 752152 - DIESEL ENGINE



Sample No: VCP437075
Oil Type: {unknown}
Job No: T AND K

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP437075	 	
Sample Date		15 Mar 2024	 	
Machine Hours		499	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CONDI	TION			
Visc @ 100°C	cSt	<b>10.8</b>	 	
Base Number (BN)		<b>6.1</b>	 	
Oxidation (PA)	%	53	 	
Oxidation (FA)	70	<b>J</b> J	 	
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	 	
Soot %	%	■ 0.2	 	
Nitration (PA)	%	74	 	
Sulfation (PA)	%	51	 	
Glycol	%	NEG	 	
Fuel	%	■0.7	 	
Silicon	ppm	<b>27</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>■3</b>	 	
WEAR ME	ZIAT			
Iron		<b>19</b>	 	
Copper	ppm	▲ 437	 	
Lead	ppm	<u> </u>	 	
Tin	ppm	<b>5</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum		■84	 	
Nickel	ppm	<b>3</b>	 	
Titanium	ppm	<1	 	
Silver	ррт	<b>0</b>	 	
Manganese	ppm	1	 	
Vanadium	ppm	0	 	
randalan	PPIII			
ADDITIVE				
Calcium	ppm	<b>2278</b>	 	
Magnesium	ppm	<b>17</b>	 	
Zinc	ppm	<b>1220</b>	 	
Phosphorus	ppm	■1061	 	
Barium	ppm	■0	 	
Boron	ppm	<b>48</b>	 	

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

No corrective action is recommended at this time. Oil and filter change at the time of sampling has been noted. Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. The copper level is abnormal. In the absence of other significant wear metals, suspect copper due to sources other than wear (i.e. cooling core). All other metal levels are typical for a new component breaking in. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10940252Signed:Don BaldridgeReport Date:26 Mar 2024

Contact/Location: KENNY HANEY - VOLVO0093



## **CONSTRUCTION EQUIPMENT**





