

CONSTRUCTION EQUIPMENT RENTAL VOLVO L180H 5785 - REAR AXLE



Sample No: VCP437929

Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

Job No: RENTAL

VOLVO	INFORMATION			
	E INFORMATION			
Sample Number		VCP437929	VCP429255	
Sample Date		23 Mar 2024	16 Oct 2023	
Machine Hours		4218	1214	
Oil Hours		0	1214	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
OIL CON	INITION			
Visc @ 40°C	cSt	43.6	41.8	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	■10	11	
Sodium		■10	2	
Potassium	ppm	■ 0		
	ppm	 U		
VOLVO				
WEAR I	METALS			
Iron	ppm	42	□ 92	
Copper	ppm	■4	3	
Lead	ppm	0	□0	
Tin	ppm	■ 0	0	
Aluminum	ppm	■ <1	П0	
Chromium	ppm	■ <1	3	
Molybdenum	ppm	7	4	
Nickel	ppm	■0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	■<1	4	
Vanadium	ppm	0	0	
	1-1	_	-	
VOLVO	VEC .			
ADDITIV	NE?			
Calcium	ppm	■3414	4161	
Magnesium	ppm	45	8	
Zinc	ppm	1446	1753	
Phosphorus	ppm	1212	1416	
Barium	ppm	0	0	
-		-110	T 121	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0093Unique No:10940887Signed:Wes DavisReport Date:25 Mar 2024

112

Boron



CONSTRUCTION EQUIPMENT





GRAPHS

